

Detroit District Operations Office P.O. Box 1027 Detroit, MI 48231-1027 (313) 226-6797 FAX - (313) 226-3519

Notice to Navigation Interests

Notice No. L07-20 Date: 22 MAY 2007

Waterway: LAKE MICHIGAN Location: MICHIGAN

CELRE-OT-T

CONDITION OF FEDERAL NAVIGATION CHANNEL NEW BUFFALO HARBOR


- 1. Surveys performed within the Federal navigation channel at New Buffalo Harbor, Michigan during May 2007, indicate the conditions shown on the following sheet.
- 2. Mariners are urged to use extreme caution in the area.
- 3. Questions regarding this notice may be directed to our Operations Office.

 Our internet address is: http://www.lre.usace.army.mil/who/operationsofficehomepage/

WILLIAM J. LEADY Lieutenant Colonel, U.S. Army District Commander

Notice to the Postmaster:

It is requested that the above notice be conspicuously and continuously posted until November 30, 2007.



ALL SOUNDINGS ARE REFERENCED TO IGLD 1985 FOR LAKE MICHIGAN, ELEVATION 577.5 FT. ABOVE MEAN SEA LEVEL AT RIMOUSKI, QUEBEC. A HYDRAULIC CORRECTOR OF 0.32 FT. WAS APPLIED.



Shoals indicate least available depth below LWD

THE INFORMATION DEPICTED ON THIS MAP REPRESENTS THE RESULTS OF SURVEYS MADE ON THE DATES INDICATED AND CAN ONLY BE CONSIDERED AS INDICATING THE GENERAL CONDITIONS EXISTING AT THAT TIME.

SURVEYED: 2 MAY 2007

NEW BUFFALO HARBOR, MI

CONDITION OF CHANNEL

ISSUED: 22 MAY 2007

U.S. Army Engineer District, Detroit